

## LACANCHE PREMIER SERVICE DESCRIPTION

The Premier Service includes the following:

- Gas and/or electric installation check
- Electric earth continuity & resistance check
- Room ventilation checks
- Remove Hob top inspect clean or replace burner assemblies/jets
- Inspection of gas valves, replace if required, or re-grease
- Inspection and replacement if required of baffle plate
- Inspection and replacement if required of hob wiring
- Inspection and replacement if required of mains & indicator neon's
- Inspection and replacement if required of control spigot
- Check hob ignitors
- Refit hob top, clean and re-commission burners
- Complete gas & working pressure
- Check operation of FFD
- Inspection of and replacement if required of oven door seals and hinge functionality
- Remove inner oven panels, inspect oven cavity
- Inspection and replacement if required of oven elements
- Inspection and replacement if required of thermostat probes
- Inspection & clean and replacement if required of oven burner
- Inspection and replacement if required of fan motors
- Inspection of terminal block connection and mains cable
- Complete oven temperature test

## COSTS

- 70cm wide £230.00 (including VAT) plus the cost of any parts used less 10% discount on the cost of parts used.
- 1000 & 1100cm wide £280.00 (including VAT) plus the cost of any parts used less 10% discount on the cost of parts used.
- 1400 & 1500cm wide £290.00 (including VAT) plus the cost of any parts used less 10% discount on the cost of parts used



- 1800cm wide £300.00 (including VAT) plus the cost of any parts used less 10% discount on the cost of parts used.
- 2200cm wide £320.00 (including VAT) plus the cost of any parts used less 10% discount on the cost of parts used.

## PREMIER SERVICE WARRANTY

Fourneaux de France Ltd Premier Service includes a 12 month Warranty from the date of the Premier Service. Fourneaux de France Ltd will repair any defects that arise (subject to the provisions listed below) due to faulty materials or workmanship in the Premier Service, free of charge during this period. Any additional parts required during the 12 month Premier Service Warranty period will be charged.

The Premier Service Warranty is subject to the following provisions: The service was carried out as per the service engineer's recommendation. The warranty does not cover: accidental damage, misuse, neglect, incorrect installation, enamelled inner or outer panels, pan stands, oven cavity parts, brass burners, burner bodies, door seals, brass/chrome or other trims. Re-commissioning of the range and gas fitting to the range are not covered by the Premier Service Warranty. Faults covered by incorrect gas supply pressure are not covered by the Premier Service Warranty. The product must be correctly installed, commissioned and operated in accordance with the instructions in the User's Manual. It must be used solely for domestic purposes, and within the boundaries of the United Kingdom. The warranty will be rendered invalid if the product is resold or has been damaged by inexpert repair. Repairs due to the appliance being incorrectly commissioned will not be covered by the warranty. Fourneaux de France Ltd disclaims any liability for accidental or consequential damages. The Premier Service Warranty is in addition to and does not diminish your statutory legal rights.